



Full Member



Lifting & Tubular Inspection - Petroleum Services



DYE PENETRANT INSPECTION REPORT

Date of Thorough Examination: 25 Aug, 2026		Date of Certificate: 28 Aug, 2026		Certificate Number: 250826/03-AD01					
Owner's Name:		NDC		Work Location:		{{Site}},Alamin			
Description of the equipment		Illustration				ID Number			
QTY (7) Lifting Cap Critical Welding Area Location: Rig Site						LC01			
Inspected Area		Critical Welding Area		✓		Inspection Category:			
		Critical Body Area							
		Full Body							
Inspection Technique		Longitudinal Magnetization		CAT III		YES		NO	✓
						CAT IV		YES	
				Client Specification				YES	✓
						Other		YES	
		If Yes							
Equipment & Technical Details									
Equipment Type		MPI TEST DETAILS				Examination Method			
		Procedure	Pole Spacing	Contrast Media	Indicator				
Permanent Magnet		TL-30	100.0 mm	White Contrast	Black Ink	Dry		Wet	✓
						Fluorescent		Visible	✓
References		- ASTM E709:2015.							
Inspection Result		- Magnetic Particle Inspection Was carried out on this item(s) mentioned above; no indications were detected at time of inspection							
Name & Qualifications of person making this report:		Name & Signature of person authenticating this report:		Stamp		Next thorough examination date must be carried out		QR Code	
Lifting Engineer Fared 		Operations Manager Mohamed Elshenawy 				25 Feb, 2027			

QF-09-07

This is an Electronic Original Certificate

For Verification Please Visit www.tetralift.com.eg

El-Obour City Industrial Zone # 1, Western Extension,
 Block 20024, Plot 18, Cairo, Egypt
 Tel.: +2 (02) 448935 16 / +2 (02) 448935 17
 Fax: +2 (02) 448 935 16

E-mail: info@tetralift.com.eg
 Website: www.tetralift.com.eg

