LEEA
Full Member

TETRA LIFT S.A.E
Lifting & Tubular Inspection - Petroleum Services

ISO 9001:2015 BUREAU VERITAS Certification

DYE PENETRANT INSPECTION REPORT

Date of Thorough Examination: 25 Aug, 2026	**Date of Certificate:** 28 Aug, 2026	**Certificate Number:** 250826/03-AD01

Owner's Name:	NDC	**Work Location:**	{{Site}},Alamin

Description of the equipment	Illustration	ID Number
QTY (7) Lifting Cap Critical Welding Area Location: Rig Site		LC01

Inspected Area	**Critical Welding Area**	✓	**Inspection Category:**				
	Critical Body Area		**CAT III**	**YES**		**NO**	✓
	Full Body		**CAT IV**	**YES**		**NO**	✓
Inspection Technique	**Longitudinal Magnetization**		**Client Specification**	**YES**	✓	**NO**	
			Other	**YES**		**NO**	✓
				If Yes			

Equipment & Technical Details

Equipment Type	MPI TEST DETAILS				Examination Method			
	Procedure	Pole Spacing	Contrast Media	Indicator				
Permanent Magnet	TL-30	100.0 mm	White Contrast	Black Ink	Dry		Wet	✓
					Fluorescent		Visible	✓

References	- **ASTM E709:2015.**
Inspection Result	- Magnetic Particle Inspection Was carried out on this item(s) mentioned above; no indications were detected at time of inspection

Name & Qualifications of person making this report:	Name & Signature of person authenticating this report:	Stamp	Next thorough examination date must be carried out	QR Code
Lifting Engineer Fared Fared	Operations Manager Mohamed Elshenawy	TETRA LIFT S.A.E Acceptable Load Testing & Inspection	25 Feb, 2027	

QF-09-07 This is an Electronic Original Certificate For Verification Please Visit www.tetralift.com.eg

El-Obour City Industrial Zone # 1,Western Extension,
Block 20024,Plot 18, Cairo, Egypt
Tel.:+2 (02) 448935 16 / +2 (02) 448935 17
Fax:+2 (02) 448 935 16
E-mail: info@tetralift.com.eg
Website: www.tetralift.com.eg

ABS ASNT EGAC DROPS